Troubleshooting

Cutting edge build-up

Cause:

Low cutting speed Excessive honing of cutting lip Bright finish cutting lip

Remedy:

Increase cutting speed Reduce cutting lip honing Have tool coated



Crumbling of outer corners

Cause:

Non-rigid conditions, insufficient workpiece clamping Excessive deviation from concentricity Interrupted cut

Remedy:

Rigid clamping of workpiece

Check and correct concentricity if possible

Reduce feed

Heavy wear and tear at flank

Cause:

Cutting speed too high Feed too low Clearance angle too small



Remedy:

Decrease cutting speed Increase feed Increase clearance angle

workpiece clamping

Interrupted cut

have been exceeded



Remedy:

Rigid clamping of workpiece

Reduce feed

Reduce tool change intervals

Apply suitable tool (see application recomendations)

Technica

Land wear

Cause:

Non-rigid conditions, insufficient workpiece clamping

Large deviation from concentricity

Back taper too small

Wrong coolant/lubrication (oil), soluble oil too thin

Remedy:

Rigid clamping of workpiece Check and correct concentricity if possible

Increase back taper

Thicken soluble iol or use neat oil



Scoring on tool body Cause:

Non-rigid conditions, insufficient workpiece clamping

Large deviation from concentricity

Interrupted cut

Abrasive workpiece material

Remedy:

Rigid clamping of workpiece Check and correct concentricity if possible Reduce feed Thicken soluble oil or use neat oil





Troubleshooting

Heavy chisel edge wear and tear

Cause:

Cutting speed too low Feed too high Excessive honing of cutting lip

Remedy:

Increase cutting speed Decrease feed Reduce cutting lip honing



Crumbling at intersection of web thinning and cutting lip

Cause:

Clearance angle too small Excessive honing of cutting lip Wrong tool type

Remedy:

Increase clearance angle Reduce cutting lip honing Apply suitable tool



Plastic deformation of outer corner

Cause:

Cutting speed too high Incorrect or no honing at corner Incorrect or no corner chamfer



Decrease cutting speed Correct honing Apply correct corner chamfer

Misalignment, axis shifting

Cause:

Non-rigid conditions, insufficient workpiece clamping Excessive deviation from

concentricity

Spotting area transverse

Chisel edge too large

Rigid clamping of workpiece

Check and correct concentricity, if possible

Use twin-fluted milling cutter for spotting



Remedy:

Reduce chisel edge

Heavy burring on breakthrough

Cause:

Feed too high

Maximum wear and tear values have been exceeded

Excessive honing of cutting lip

Remedy:

Decrease feed

Reduce tool change intervals

Reduce cutting lip honing



Unsatisfactory surface quality

Cause:

Non-rigid conditions, insufficient workpiece clamping

Excessive deviation from concentricity

Insufficient coolant

Remedy:

Rigid clamping of workpiece Check and correct concentricity, if possible Increase coolant (volume, pressure)

